



ギア比	L寸法	A寸法	B寸法
1.5 ~ 10	279	50	80
1.25 ~ 100	295	66	96
1.150 ~ 300	310	81	111