



| ギア比 | L寸法 | A寸法 | C寸法 |
|----------------|-------|------|-----|
| 1 : 6 ~ 10 | 107.7 | 19 | 12 |
| 1 : 18 ~ 30 | 110.2 | 21.5 | 9.5 |
| 1 : 50 ~ 100 | 112.7 | 24 | 12 |
| 1 : 120 ~ 300 | 115.2 | 26.5 | 9.5 |
| 1 : 400 ~ 1000 | 117.7 | 29 | 12 |